




OH $111\frac{1}{2}$ WH—
FH84 WD—

Panel 30	$41\frac{1}{2}$ $H26\frac{1}{2}$ $D22\frac{1}{2}$	36 $H26\frac{1}{2}$ $D22\frac{1}{2}$	$41\frac{1}{2}$ $H26\frac{1}{2}$ $D22\frac{1}{2}$	30 $H26\frac{1}{2}$ $D22\frac{1}{2}$
Panel 30	41 $H22$ $D15\frac{1}{2}$	36 $H22$ $H1\frac{1}{2}$ $D15\frac{1}{2}$ 35	41 $H22$ $D15\frac{1}{2}$	T30 C/S 24 micro 30
	DB $44\frac{1}{4}$	B30 C/T35 S/O 30	DB $44\frac{1}{4}$	

